

2018

J.M. Stuart Station
Ash Pond 7 Annual Inspection
ODNR File No.: 8535-002



Prepared by:
John Hendrix, PE



Date: December 21, 2018

Purpose

I have conducted the following annual inspection in compliance of the Federal CCR Rule, 40 CFR Part 257 and Ohio Department of Natural Resources OAC 1501-21.

Statement of Qualifications

I am a practicing Civil/Geotechnical Professional Engineer registered in the State of Ohio employed by AES Ohio Generation, LLC. I am experienced in the design, maintenance and operation of earthen dams and impoundments.

Review of Impoundment Documentation [§ 257.83(b)(1)(i)]

Design, History, and Operation of the Facility

Ash Pond 7 is an upland reservoir that was constructed in 1978. This pond is used for settling wet sluiced fly ash produced from the combustion of coal in the station generating units. This pond is rectangular and incised to the north and to the west. The dam to the south side of Pond 6 is the north side of Pond 7. It has an area of 38.4 acres at the crest, is 39.5-feet deep and has a volume of 42,400,000 cubic feet to the crest. In c1983, after initial filling, a portion of Pond 7 was excavated and lined to form Pond 7A. Another portion of the original pond 7 was excavated and the remaining area (approximately 25%) capped leaving the remainder of the pond for ash sluicing. This portion of Pond 7 is periodically drained and the settled fly ash excavated which is then sent to a dry ash landfill. As originally constructed the normal operating level of this pond was two feet below the crest. In 2013 the outlet of this pond was replaced to provide a Maximum Operating Level of three feet. This new outlet is composed to two, 36-inch high density polyethylene (HDPE) pipes incased in concrete with a concrete flume structure at the inlet and concrete headwall at the outlet.

Pond 7A, located in the northeast corner of the original Pond 7, was excavated to elevation 515.0 feet. The area is approximately three acres and is 16.5-feet deep from the crest. Pond 7A overflow is a concrete weir with a skimmer. The weir discharges to the Ohio River through a 36-inch HDPE pipe that replaced the previous corrugated metal pipe in 2015. And in 2017 repairs along the toe were made and the river bank stabilized on the eastern portion of the south dam.

J. M. Stuart Station stopped operating on May 24, 2018; therefore, this impoundment is not expected to receive any more ash or water.

Periodic Inspections

A thorough review of weekly facility inspections was conducted. These periodic inspections do not indicate any structural weakness. It was noted that there was some difficulty reestablishing vegetation following the repairs late in 2107. This area should continue to be monitored during the coming year.

Previous Structural Assessments

The report on Initial Periodic Structural Stability Assessment Pond 7 J.M. Stuart Electric Generating Station by Haley & Aldrich in 2016 was reviewed as well as annual inspections from previous years, a 2009 inspection by Civil Environmental Consultants, a 2010 structural assessment by BBC&M and the 2013 and 2018, 5-year inspection reports by Ohio Department of Natural Resources.

Visual Inspection of Impoundment [§ 257.83(b)(1)(ii)]

The Pond 7 dam is in good structural condition. Noted erosion along the shoreline of the river and the toe of the dam has been addressed. Earth choked riprap had been added along the shoreline of the Ohio River and the eroded toe area restored.

Changes in Geometry [§ 257.83(b)(2)(i)]

There were no changes to the upstream face of the dam. Rock erosion protection is in place along the south dam is in good condition. There were no changes to the geometry of the downstream face of the pond dam or other indications of structural weakness. Repairs made in 2017 are in good condition. Slopes have no indication of deformation or other indicators of instability.

Instrumentation [§ 257.83(b)(2)(ii)]

Pond 7 is equipped with a staff gauge located at the Pond 7 outlet. A gauge is also located adjacent to the Pond 7A weir. These gauges are in good condition.

Structural Weakness [§ 257.83(b)(2)(vi)]

No indication was found of an actual or potential structural weakness of the CCR unit or any existing condition that was disrupting or had the potential to disrupt the operation and safety of the CCR unit and appurtenant structures.

Other Changes [§ 257.83(b)(2)(vii)]

No changes were found to the CCR unit which could affect the stability or operation of the impounding structure since the previous annual inspection. Since operation and active sluicing of CCR material to the pond has stopped, the water level has been lowered to approximately 10 feet below the crest.

Visual Inspection of Hydraulic Structures [§ 257.83(b)(1)(iii)]

The hydraulic structures for this pond are twofold. Pond 7 outlets to Pond 6 through two 30-inch HDPE pipes encased in concrete with concrete inlet and outlet structures. This structure replaced the former structure in 2014. Pond 7A has a 40-foot wide concrete weir to maintain the pond level. This weir outlets to the Ohio River through a new 36-inch HDPE pipe. Pond 7 also has a grass-lined channel emergency spillway that would convey water directly to Pond 7A to by-pass Pond 6. All hydraulic structures are in good condition.

Water and Material Depths and Volumes

[§ 257.83(b)(2)(iii), § 257.83(b)(2)(iv), § 257.83(b)(2)(v)]

Physical Parameters of Impoundment		
Depth of water	31	Feet
Maximum Depth of Water	36.5	Feet
Minimum Depth of water	0	Feet (by pumping only)
Elevation of water	521	Feet (review of weekly inspection reports show normal fluctuation of the depth/water level)
Storage Capacity	2,240,000	Cubic Yards, Crest Full Volume
	1,910,000	Cubic Yards, (to three-foot freeboard)
Volume of water	505,000	Cubic Yards
Volume of CCR	1,719,000	Cubic Yards (sluiced ash)

Appendix A

CCR Rule Requirements for Impoundment Annual Inspections

257.83 (b) Annual inspections by a qualified professional engineer.

(1) If the existing or new CCR surface impoundment or any lateral expansion of the CCR surface impoundment is subject to the periodic structural stability assessment requirements under § 257.73(d) or § 257.74(d), the CCR unit must additionally be inspected on a periodic basis by a qualified professional engineer to ensure that the design, construction, operation, and maintenance of the CCR unit is consistent with recognized and generally accepted good engineering standards. The inspection must, at a minimum, include:

- (i) A review of available information regarding the status and condition of the CCR unit, including, but not limited to, files available in the operating record (e.g., CCR unit design and construction information required by §§ 257.73(c)(1) and 257.74(c)(1), previous periodic structural stability assessments required under §§ 257.73(d) and 257.74(d), the results of inspections by a qualified person, and results of previous annual inspections);
- (ii) A visual inspection of the CCR unit to identify signs of distress or malfunction of the CCR unit and appurtenant structures; and
- (iii) A visual inspection of any hydraulic structures underlying the base of the CCR unit or passing through the dike of the CCR unit for structural integrity and continued safe and reliable operation.

(2) *Inspection report.* The qualified professional engineer must prepare a report following each inspection that addresses the following:

- (i) Any changes in geometry of the impounding structure since the previous annual inspection;
- (ii) The location and type of existing instrumentation and the maximum recorded readings of each instrument since the previous annual inspection;
- (iii) The approximate minimum, maximum, and present depth and elevation of the impounded water and CCR since the previous annual inspection;
- (iv) The storage capacity of the impounding structure at the time of the inspection;
- (v) The approximate volume of the impounded water and CCR at the time of the inspection;
- (vi) Any appearances of an actual or potential structural weakness of the CCR unit, in addition to any existing conditions that are disrupting or have the potential to disrupt the operation and safety of the CCR unit and appurtenant structures; and
- (vii) Any other change(s) which may have affected the stability or operation of the impounding structure since the previous annual inspection.

Appendix B

Reference Documents Reviewed

- ❖ Operation Maintenance and Inspection Manual
- ❖ Emergency Action Plan
- ❖ Structural Analysis
 - Initial Periodic Structural Stability Assessment Pond 7 J.M. Stuart Electric Generating Station by Haley & Aldrich in 2016
- ❖ Previous inspection reports
 - CEC 2009
 - ODNR 2013, 2018
 - CHA 2010
 - BBCM 2010
- ❖ Drawings
 - 300-12-1020B
 - 300-12-1020C
 - 300-12-1315 sh 1
 - 300-12-1315 sh 2
 - 300-46-1104
 - 300-46-1105
 - 300-46-1106

Appendix C
Inspection Check List

Dam Field Inspection Report

DAM/IMPOUNDMENT ANNUAL FIELD INSPECTION FORM

Unit Name: Pond 7

Facility Name: J.M. Stuart Station

ODNR File No.: 8535-002

CCR Unit

ACTION

ODNR Hazard Classification: I II III IV N/A

Impoundment Type: Incised Upland Lake

Description: Located south of Pond 6 and east of Pond 3A along the Ohio River.

Approximately one fourth of this pond is permanently closed, a portion of which was excavated and lined for use as a tertiary settling pond (Pond 7A) for ash sluice water.

Inspection Date(s): November 2018

Weather/Surface Conditions During Inspection: mostly cool and dry.

Freeboard: 4.5'

NONE
 MONITOR
 MAINTENANCE
 ENGINEER

UPSTREAM SLOPE

Gradient: Horizontal: 2.5 Vertical: 1 (est. meas.)

VEGETATION

Trees:

DESCRIPTION AND LOCATION:

Brush:

DESCRIPTION AND LOCATION:

Ground Cover:

DESCRIPTION: Pond 7 has grass cover on the upstream slope. Stone had been added to the slope on the south dam. Pond 7A is covered with No 2 stone

CONDITION: Pond 7 grass cover is sparse along the north side of the pond. Stone on the south dam is in good condition. Pond 7A is in good condition.

SLOPE PROTECTION

TYPE or NONE:

DESCRIPTION: Pond 7 - Has small riprap along the south dam and is partially covered with deposited CCR material. Pond 7A - covered with No. 2 Limestone.

CONDITION: Good in 7A basin.

EROSION:

DESCRIPTION AND LOCATION: Pond 7 has several erosion rills on both the north and south dam. The east and west dams are in good condition. Pond 7A is in good condition.

INSTABILITIES: (SLIDES, CRACKS, BULGES, etc.)

SLIDES/SLOUGHS:

DESCRIPTION AND LOCATION:

CRACKS:

DESCRIPTION AND LOCATION:

BULGES:

DESCRIPTION AND LOCATION:

OTHER:

DESCRIPTION AND LOCATION:

OTHER (rodent burrows, ruts, etc.)

DESCRIPTION AND LOCATION:

DESCRIPTION AND LOCATION:

	ACTION			
	NONE	MONITOR	MAINTENANCE	ENGINEER
DESCRIPTION AND LOCATION:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
CREST Length: 3,136 Width: 16' design, 26 ft effective (est. meas.)				
GROUND COVER:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION: Dense graded stone (ODOT 304)				
CONDITION: Good				
EROSION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION:				
INSTABILITIES: (SLIDES, CRACKS, BULGES, etc.)				
CRACKS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION:				
RUTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION:				
POT HOLES:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION:				
OTHER	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION:				
MONITORING INSTRUMENTATION:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION: Staff gauge at the outlet structure				
CONDITION:				
ALIGNMENT:				
CONDITION: Alignment of dam indicates no deflection horizontally or vertically.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
OTHER (rodent burrows, ruts, etc.)				
DESCRIPTION AND LOCATION:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DOWNSTREAM SLOPE Gradient: Horizontal: 2' to 3' Vertical: 1 (est. meas.)				
VEGETATION				
Trees:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION: none				
Brush:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION: none				
Ground Cover:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION: Grass				
CONDITION: The downstream slope now has a substantial grass cover. There are silt deposits on the toe from frequent flooding of the adjacent Ohio River that were not well vegetated.				
EROSION	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION: Some erosion rills were observed near the 013 outfall				

	ACTION			
	NONE	MONITOR	MAINTENANCE	ENGINEER
structure. Monitor until repairs can be made. Repair and reestablish vegetation in the spring.				
INSTABILITIES: (SLIDES, CRACKS, BULGES, etc.)				
SLIDES/SLOUGHS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION:				
CRACKS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION:				
BULGES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION:				
OTHER	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION:				
SEEPAGE/WET AREA	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION:				
EMBANKMENT DRAINS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION:				
CONDITION:				
MONITORING INSTRUMENTATION:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION: Two vibrating wire piezometers were installed for the 2010 investigation and are no longer active.				
CONDITION: not active				
OTHER (rodent burrows, ruts, etc.)				
DESCRIPTION AND LOCATION:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION AND LOCATION:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
HYDRAULIC STRUCTURES				
STRUCTURE:				
DESCRIPTION: Pond 7 Principle Spillway, Rebuilt in 2013				
INLET	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION: Reinforced concrete channel, ungated				
CONDITION: Structure is in good condition.				
OBSTRUCTION NOTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO) DESCRIBE IF YES:				
CONDUIT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION: Two 30 inch HDPE pipes encased in reinforced concrete.				
CONDITION: Good condition.				
SEEPAGE NOTED: (<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO) DESCRIBE IF YES:				
OUTLET	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DESCRIPTION: Concrete headwall.				
CONDITION: Good condition.				
EROSION NOTED: (<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO) DESCRIBE IF YES:				

ACTION

NONE
MONITOR
MAINTENANCE
ENGINEER

STRUCTURE:

DESCRIPTION: Pond 7A Principle Spillway

INLET

DESCRIPTION: 40' side, reinforced concrete overflow weir

CONDITION: Structure is in good condition

OBSTRUCTION NOTED: (YES NO) DESCRIBE IF YES:

CONDUIT

DESCRIPTION: One 36" HDPE pipe on 6% slope

CONDITION: Good condition. (Pipe was slip-lined in 2015 with HDPE and grout filled annular space)

SEEPAGE NOTED: (YES NO) DESCRIBE IF YES:

OUTLET

DESCRIPTION: Concrete headwall.

CONDITION: Good

EROSION NOTED: (YES NO) DESCRIBE IF YES:

STRUCTURE:

DESCRIPTION: Emergency Overflow from Pond 7 to Pond 7A

INLET

DESCRIPTION: Wide grass-vegetated, channel.

CONDITION: Good condition.

OBSTRUCTION NOTED: (YES NO) DESCRIBE IF YES:

CONDUIT

DESCRIPTION: Wide grass-vegetated, channel.

CONDITION: Good condition.

SEEPAGE NOTED: (YES NO) DESCRIBE IF YES:

OUTLET

DESCRIPTION: Wide grass-vegetated, channel.

CONDITION: Good condition.

EROSION NOTED: (YES NO) DESCRIBE IF YES:

Appendix D

CCR Unit Maintenance Recommendations

1. Repair erosion on downstream slope near the 013 outfall structure in the Spring then reestablish vegetative cover.
2. Continue with pond closure conceptual design evaluation.

Continued Monitoring

1. Monitor erosion on downstream slope until repairs can be made. Monitor grass vegetative cover after repairs until it is reestablished.